

PRESSURE/TORQUE CONVERSION CHART

30HP

PRESSURE IN PSI	FT. LBS.	N-m
1500	3839	5205
1600	4123	5590
1800	4693	6363
2000	5262	7134
2200	5845	7925
2400	6428	8715
2600	7011	9506
2800	7594	10296
3000	8177	11086
3200	8757	11873
3400	9337	12659
3600	9916	13444
3800	10496	14230
4000	11076	15017
4200	11666	15817
4400	12255	16615
4600	12845	17415
4800	13434	18214
5000	14024	19014
5200	14618	19819
5400	15212	20624
5600	15806	21430
5800	16400	22235
6000	16994	23040
6200	17591	23850
6400	18187	24658
6600	18784	25467
6800	19380	26275
7000	19977	27085
7200	20569	27887
7400	21161	28690
7600	21752	29491
7800	22344	30294
8000	22936	31097
8200	23528	31899
8400	24120	32702
8600	24712	33505
8800	25304	34307
9000	25896	35110
9200	26489	35914
9400	27082	36718
9600	27675	37522
9800	28268	38326
10000	28861	39130